

Service Bulletins (Airworthiness Directives) for Yak-18T

| Bulletin No. | Date of issue | Contents | Applicability, S/N | Performed by | Performing term |
|--------------|---------------|---|------------------------------------|--|-----------------|
| 1E | 08.01.75 | "Varly" battery body repair | | Overhaul factory | MOH |
| 001-DM | 31.10.75 | Replacement of the SBSE-77 fuel meter with the SBES2077E fuel meter | 0601-0504 | Overhaul factory | MOH |
| 002-DK | 29.05.75 | Replacement of the engine mount ring for the reinforced one | 0601-2007 | Overhaul factory | MOH |
| 003-DK | 29.05.75 | Replacement of the 4211-93 linkage in the 4211-90 damper | 0601-0907 | Aircraft manufacturer/ Overhaul factory | MOH |
| 004-R | 29.05.75 | Replacement of undercarriage shock absorber pistons No.4111-14 and No.4211-18. | 0601-0306 | Overhaul factory | MOH |
| 005-E | 09.07.75 | Manuals clarification | 0101-1008 | Maintenance organization | 1975 |
| 006-DK | 06.06.75 | Replacement of landing gear uplock springs No.4115 and No.4215 | 0601-0906 | Aircraft manufacturer | MOH |
| 007-DM | 11.06.75 | Replacement of the M-14 engine with the M-14P | 0601-0204 | Maintenance organization | MOH |
| 008-DK | 19.05.76 | Fire shut-off valves sealing | 0601-0106 | Maintenance organization | If necessary |
| 009-DK | 29.07.76 | Replacement of the edge former No.1014-07 on the wall of the rib No.4 in the wing center section | 0601-2008 | Overhaul factory | MOH |
| 010-DK | 13.09.76 | Installation of the oil cooler winterization blank No.6205-30A | 0601-2008 | Aircraft manufacturer | 30.09.1977 |
| 012-DK | 23.03.76 | Reinforcement of the front spar wing attachment point | 0601-1008 | Overhaul factory | MOH |
| 014-E | 29.09.76 | Manuals clarification | 0101-0110 | Maintenance organization | 31.01.1977 |
| 015-DK | 29.04.77 | 1. Pitot attachment reinforcement 2. Replacement 7703-01 | 0601-0814 0601-0814 | Overhaul factory | MOH |
| 016-DK | 13.07.76 | Replacement of throttle lever attachment and friction unit | 0601-2007 | Overhaul factory | MOH |
| 017-DK | 23.11.76 | Holes in the carburetor inlet choke | 0601-0610 | Aircraft manufacturer | MOH |
| 021-DK | 29.03.77 | Replacement of the trim tab and installation of additional balance weight on the elevator | 0601-0812 | Overhaul factory | MOH |
| 022-DK | 06.04.77 | Replacement of the governor stop-screws bracket with the reinforced one | 0601-2014 | Overhaul factory | MOH |
| 024-DK | 06.04.77 | Replacement of the collective tank drain valve No.6100-170 for the drain valve No.600500A | 0601-1807 | Overhaul factory | MOH |
| 025-DK | 29.04.77 | Stabilizer reinforcement within the brace attachment area | 0601-2013, 0401 | Overhaul factory | MOH |
| 026-DK | 05.03.77 | Fire wall reinforcement within the area of PK-45 attachment | 0101, 0401, 0601-2012 | Overhaul factory | MOH |
| 027-DK | 05.03.77 | 1. Enlargement of the aileron skin cutout 2. Installation of the additional access door in the cockpit floor | 0101, 0401, 0601-2013 0601-2014 | Overhaul factory | MOH |
| 028-DK | 06.05.77 | 1. Installation of the plate on the wing center section leading edge 2. Replacement of three SP-1 AC circuit breakers with SP-2B AC circuit breakers | 0101-2014 0101-0313 | Overhaul factory | 30.12.77 |
| 029-DK | 19.01.77 | Landing gear inspection | 0601-0807 | Aircraft manufacturer | 28.02.77 |

| | | | | | |
|-----------------------|----------|---|---|---|--------------|
| 030-DK | 26.05.77 | Replacement of control surfaces attachment units with removable studs | 0101-2014 | Overhaul factory | MOH |
| 031-DK | 25.03.77 | Replacement of the oil cooler thermovalve with the reducing valve | 0101-1212 | Overhaul factory | MOH |
| 032-DK | 29.04.77 | Wing center section reinforcement (13 different modifications) | Refer to SB | Overhaul factory | MOH |
| 033-DK | 29.04.77 | Replacement of the emergency air bottle supporting cup | 0601-2013 | Overhaul factory | MOH |
| 034-DK | 27.06.77 | 1. Fuselage modification for the installation of 7512-0 fans 2. Reinforcement of gills lip attachment 3. Reinforcement of gills vanes attachment points | 0101-2010 0101-2009 0101-2013 | Overhaul factory | MOH |
| 035-DK | 26.05.77 | 1. Improving AM-800K landing gear micro switch reliability 2. Replacement of gills control arm with the reinforced one 3. Improving of brake cable terminations 4. Adjusting air system reducing valve | 0101, 0401, 0601-1009 0101, 0401, 0601-2015 0101, 0401, 0601-2010 0101, 0401, 0601-21921 | Overhaul factory Overhaul factory Overhaul factory Aircraft manufacturer | MOH |
| 037-DK | 01.06.77 | Replacement of the stabilizer attachment fork-bolt No. 3000-02 | 0101, 0401, 0601-0614 | Aircraft manufacturer | 30.09.77 |
| 038-DK | 01.09.77 | Replacement of bushings No.4210-05 in upper part of nose landing gear bracing strut | 0101, 0401, 0601-2014 | Overhaul factory | MOH |
| 039-DK | 27.02.78 | Replacement of 2KNR buttons with PK2S-2 buttons for "Radio" and "Intercom" | 0101, 0402 0601-1415 | Overhaul factory | MOH |
| 040-DK | 02.12.77 | Installation of the reinforcement plate on the pilot's seat sliding rail | 0101, 0601-2015 | Overhaul factory | MOH |
| 041-DK | 09.02.78 | Elimination of plays in rudder pedals mechanism | 0102, 0101-2015 | Overhaul factory | MOH |
| 042-DK | 01.09.77 | Replacement of the wing center section diaphragm post with the reinforced post | 0101, 0401, 0601-0614 | Overhaul factory | MOH |
| 043-DK | 02.12.77 | Reinforcement of the carburetor inlet pipe | 0101, 0401, 0601-23617 | Overhaul factory | MOH |
| 045-E (6328/185-E) | 17.07.78 | Increasing the life time and calendar life for nose landing gear jack | All | Information bulletin | |
| 046-DK | 18.07.79 | Fin reinforcement | 0101, 0601-23961 | Overhaul factory | MOH |
| 047-E | 23.03.78 | Manuals clarification | 0115-2015 | Operator | 31.08.78 |
| 048-DK | 05.01.78 | Replacement of elevator flanges for reinforced ones | 0101, 0401, 0601-23961 | Overhaul factory | MOH |
| 049-DK | 18.03.79 | Replacement of aileron's and elevator's brackets due to the replacement of MP-5 alloy with the AL-19 alloy | 0401, 0601-1006 Part 1: 0601-1706 | Overhaul factory | MOH |
| 050-DK | 02.12.78 | Installation of additional stabilizer attachment point | 0401, 0601-1018 | Overhaul factory | MOH |
| 051-DK | 24.05.78 | Lower engine cowling reinforcement | 0401, 0601-2016 | Overhaul factory | MOH |
| 052-DK | 09.06.78 | Reinforcement of cockpit ventilation pipes, compressor and generator cooling ducts | 0101, 0401, 0601-2014 | Overhaul factory | MOH |
| 053-DK (6328/193) | 25.04.78 | Replacement of undercarriage jacks No.4114-00 | Till 06067 | Aircraft manufacturer | 31.08.79 |
| 054-DK | 06.02.78 | Oil tank leaks elimination | 0101, 0601-2014 | Maintenance organization | If necessary |
| 055-DK | 08.02.78 | Replacement of fuel tanks 6101- 001V with reinforced ones 6101- 00D | 0601-1111 | Overhaul factory | 30.12.79 |

| | | | | | |
|-----------------------|----------|--|------------------------------|---------------------------|--|
| 057-DK | 10.08.78 | Clarification of bulletin No. 32-DK | 0601-0415 | Overhaul factory | On SB receipt |
| 058-DK | 02.12.78 | Fuel system modification: 1. Replacement of the tee-piece No.6100-06 with the new shape tee-piece 2. Installation of the additional attachment point for the pipe No.6100-00 | 0601-23617 0601-2011 | Overhaul factory | 30.12.79 |
| 059-DK | 09.06.78 | Installation of the IL-611-150 regulator in the charging device | 0601-0516 | Aircraft manufacturer | 31.12.79 |
| 060-DK | 09.06.78 | Installation of plates on the wing center section skin near the landing flap | 0601-21921 | Overhaul factory | MOH |
| 061-DK | 10.08.78 | Replacement of aluminium pipes with steel pipes | 0101, 0401 0601-23015 | Overhaul factory | MOH |
| 062-DK | 30.11.78 | Installation of the plate on the relay box | 0101, 0401, 0601-23617 | Overhaul factory | MOH |
| 063-DK | 10.04.79 | Airplane modification for the installation of engine equipped with M9F magneto | 0101, 0601-23516 | Overhaul factory | MOH |
| 064-IK | 31.07.78 | Introduction of new airplanes numbering | 21517 and up | Aircraft manufacturer | permanent |
| 065-DK | 21.02.79 | 1. Fuel tank compartment inspection and replacement of bracket 2006- 11 2. Undercut of the middle stringer of the removable panel of the tank compartment. | 0601-1016 0601-30003 | Aircraft manufacturer | In accordance with the plan of Civil Aviation Ministry |
| 066-DK | 10.08.78 | Clarification of serial numbers of airplanes to be modified in accordance with bulletins 35, 43, 48, 51 DK | 0601-2018 | Refer to Service Bulletin | |
| 067-DK (6328/220R) | 05.09.78 | Changing of the attachment of main landing gear shock absorber obturator | Shock absorber till 01.04.77 | Overhaul factory | MOH |
| 068-DK | 10.08.78 | Extending the validity of the bulletin No.15-DK | 1108-0814 | Aircraft manufacturer | MOH |
| 069-E | 08.06.79 | Manuals clarification | 0601-30016 | Information bulletin | |
| 070-E | 21.02.79 | 1. Extending air bottles life time and calendar life. 2. Interchangeability of fuel meters SBES-2077A and SBES- 207B | all 0601-0813 | Information bulletin | |
| 071-DK | 29.06.79 | Replacement of exhaust pipes made from Steel 20 with exhaust pipes made from 12H18N10T | 0601-30928 | Aircraft manufacturer | From 2nd MOH |
| 072-DK | 08.06.79 | Modification of fuel breathing system in order to make separate breathing | 0601-2007 | Overhaul factory | MOH |
| 073-DK | 22.09.79 | Reinforcement of the elevator trim tab control system | 0601-34032 | Overhaul factory | MOH |
| 074-DK | 08.06.79 | 1. Installation of the additional pneumatic system non-return valve 2. Separation of emergency air system from the main one | 0401, 0601-30216 | Aircraft manufacturer | 31.12.80 |
| 075-IK | 31.01.79 | Structural changes of airplanes | 1313-23617 | Information bulletin | |
| 076-DK | 12.03.79 | Replacement of attachment bolts for wing center section fairing | 0401, 0601-2014 | Overhaul factory | MOH |
| 077-DK | 18.06.79 | Installation of the plate on cockpit doors within the upper hinge area | 0601-32816 | Overhaul factory | MOH |
| 078-DK | 10.02.80 | Replacement of the door lock fixing arm with the longer arm No.0134-07 | 0601-37290 | Overhaul factory | MOH |
| 079-DK | 26.07.79 | Installation of the plate on the shape No.0100-21-1,-2 on the 9th bulkhead | 0601-32230 | Overhaul factory | MOH |

| | | | | | |
|----------------------|----------|---|-------------------------|-----------------------|--------------------------|
| 080-R | 23.10.79 | Addendum to „The MOH manual“ | all | Overhaul factory | On SB receipt |
| 081-E | 08.06.79 | Manuals clarification | 0601-32875 | Operator | On SB receipt |
| 082-E | 24.04.79 | Increasing of the life time before the first MOH for lower arms of undercarriage bracing struts | all | Operator | |
| 084-DM | 21.10.82 | Installation of SARPP-12K flight data registration system | 0601-41817 | Overhaul factory | MOH |
| 085-DK | 05.04.80 | Addendum to the bulletin No.40-DK 1. Installation of the reinforcement plate on the rail No.7509-211 2.Reaming seat fixation holes 8x9 in seat rails | 0601-2005 0601-37290 | Overhaul factory | MOH |
| 086-DK | 13.02.80 | Emergency door jettison mechanism modification | 0601-40212 | Overhaul factory | MOH |
| 087-BD | 03.06.82 | Replacement of the metal oil cooler fairing with the glass fiber fairing | 0601-47287 | Overhaul factory | MOH |
| 088-E (6328/249E) | 14.06.79 | Landing gear life time extension | all | Operator | On SB receipt |
| 089-R (6328/254R) | 24.10.79 | Replacement of the shock absorber ring No.4111-11 with the ring No.4111-00 | 4111-00 till 01.04.79 | Overhaul factory | MOH |
| 81127- R | 02.04.82 | Addendum to the carburetor repair technology | All | Information bulletin | |
| 090-DK | 07.02.80 | AK-50 compressor cooling improvement | 0601-0910 | Overhaul factory | MOH |
| 091-E | 07.06.80 | Manuals clarification | 0114-34016 | Operator | On SB receipt |
| 092-DK | 22.09.81 | Replacement of the landing gear switch bracket with the improved one | 0601-37219 | Overhaul factory | MOH |
| 093-DK | 19.12.80 | Reinforcement of the landing flap hinge | 0401, 0601-2015 | Overhaul factory | MOH |
| 094-DK | 13.06.80 | Replacement of the terminal in the trim tab neutral position warning system | 0401, 0601-37290 | Overhaul factory | MOH |
| 095-DK | 13.11.80 | Installation of the additional instrument panel shock mount | 0601-34139 | Overhaul factory | MOH |
| 096-DM | 24.11.80 | Replacement of the "Landysh-5" radio with "Baklan" radio | 0601-37192 | Overhaul factory | MOH |
| 097-DK | 22.08.80 | Reinforcement of the wing center section skin along the rib No.4 (if cracks occur) | 0601-1012 | Overhaul factory | MOH or if cracks occur |
| 098-DK | 25.12.80 | Reinforcement of the landing flap within the area of pneumatic jack attachment | 0601-40019 | Overhaul factory | MOH |
| 099-DK | 22.09.81 | Elevator structure reinforcement | 0601-44604 | Overhaul factory | MOH |
| 100-R | 22.07.80 | MOH documentation clarification | 0601-34066 | Operator | 3 month after SB receipt |
| 101-E | 16.04.81 | Manuals clarification | 0114-40044 | Operator | 1 month after SB receipt |
| 102-DK | 20.04.81 | Reinforcement of relay box attachment points | 0601-40044 | Overhaul factory | MOH |
| 103-DK | 20.04.81 | Replacement of fuel tank aluminium attachment bands with steel bands | 0601-30928 | Overhaul factory | 30.06.82 |
| 104-DK | 04.02.81 | Clarification of bulletins No.61-DK and No.86-DK | see 061-DK & 086-DK | Operator | |
| 105-DK (6328/308) | 22.09.81 | Replacement of faulty cylinders No. 4114-00A with cylinders No.4114-00B | 4114-00A till 11/80 | Overhaul factory | 22.03.83 |
| 106-DK | 24.09.81 | Reinforcement of the rudder structure within the trim tab attachment area | 0601-44604 | Overhaul factory | MOH |
| 107-DK | 10.11.81 | Installation of aircraft electric grounding device | 0601-34062 | Aircraft manufacturer | 31.12.82 |
| 108-DK | 03.06.82 | Reinforcement of the carburetor intake | 0601-50376 | Overhaul factory | MOH |

| | | | | | |
|----------------------|----------|---|---------------------------------------|-------------------------------------|------------------------------|
| 109-IK | 10.06.81 | Major structural changes of airplane S/N 22202023624 through 22202044794 | 23624-44794 | Information bulletin | |
| 110-E (6328/335E) | 12.11.81 | Reducing landing gear shock absorbers charging pressure | 0601-0730 | Maintenance organization | 30.12.82 |
| 111-E | 21.05.82 | Manuals clarification | 0114-47817 | Information bulletin | |
| 112-DK | 22.06.82 | Modification of pilots' seat control cable termination | 0601-47389 | Overhaul factory | MOH |
| 113-DK | 03.06.82 | Replacement of brackets, which attach ribs to the rear spar | 0601-44794 | Overhaul factory | MOH |
| 114-DK | 30.06.82 | 1. Replacement of pneumatic panel No.5801-00A with the pneumatic panel No.5801-00B 2. Installation of the main air bottle drain system 3. Transfer of the main air bottle to the left part of luggage compartment | 0601-30216 0601-32816 0601-2006 | Overhaul factory | MOH |
| 115-BU | 14.07.82 | Replacement of AZP-1BM with AZP-A2 | 0601-44812 | Maintenance organization | If found inop |
| 116-DM | 21.01.84 | Critical angle of attack warning installation | 0601-47817 | Aircraft manufacturer | MOH |
| 117-DK | 29.12.81 | Replacement of outer and middle aileron hinges | 0601-49488 | Aircraft manufacturer | 30.06.83 |
| 118-DA | 25.11.81 | Periodical inspection of the middle aileron hinge bracket | 0601-49488 | Maintenance organization | During scheduled maintenance |
| 119-E | 28.04.82 | Manual clarification (elimination of summer heating) | 0601-47817 | Information bulletin | |
| 120-BR | 21.05.82 | MOH Manual text clarification | All | Information bulletin | |
| 121-BD | 04.10.82 | Preventing of cracks and galling of rollers No.5200-20 located on the bulkhead No.12 | 0601-50376 | Overhaul factory | MOH |
| 122-BR | 04.10.82 | MOH Manual clarification (rudder control) | | Information bulletin | |
| 123-BD | 13.05.83 | Preventing the aileron inboard hinge bolt No.2000-19 wear out | 0601-34139 | Overhaul factory | MOH |
| 124-BR | 03.05.83 | MOH Manual clarification (bulletins No.87 and No.117) | All | Information bulletin | |
| 125-BE | 14.05.82 | Manual clarification (regarding the replacement of AEP-MB with AEP- A2) | All | Information bulletin | |
| 126-BR | 14.07.82 | Manual clarification (regarding AZP) | All | Information bulletin | |
| 127-BD | 04.10.82 | Elimination of engine cowling shapes wear out | 0601-32230 | Aircraft manufacturer | 30.06.83 |
| 128-BD | 18.10.82 | Replacement of attachment eyebolts on the aileron outboard bracket | 0601-51822 | Overhaul factory | MOH |
| 129 BD | 28.03.83 | Replacement of the pitot attachment tube with the reinforced one | 0601-55418 | Overhaul factory | MOH |
| 130-BR | 09.09.82 | Clarification of Operational and MOH Manuals regarding aileron's attachment brackets | 0601-55612 | Maintenance organization | MOH |
| 131-BE | 28.07.83 | Clarification of Operational and MOH Manuals regarding the SSKUA-1 flight data recording system | All | Maintenance organization, Operator | After SB 116-DM |
| 132-BD | 04.03.83 | Replacement of exhaust collector and exhaust pipe repair | 0601-55612 | Overhaul factory | If necessary |
| 133-BD | 20.07.83 | Expanding of the bulletin No.32-DK application | 0112-55612 | Overhaul factory | MOH |
| 134-BD | 20.07.83 | Installation of Teflon washers for the wing fairing attachment bolts | 0601-44794 | Cancelled by the bulletin No.195-BD | |
| 135-BD | 23.11.83 | Replacement of the lever No.6500-71 with the reinforced one | All | Aircraft manufacturer | MOH after 1500 hours |

| | | | | | |
|--------|----------|---|------------------------|---|--------------------------|
| 136-BD | 04.11.83 | Preventing fin fabric skin ruptures | 0601-55612 | Cancelled by the bulletin No.200-BD | |
| 138-BE | 05.11.83 | Manuals clarification (installation and dismounting of landing gear jacks) | 0601-55612 | Overhaul factory | On SB receipt |
| 139-BR | 23.02.84 | MOH Manual clarification (throttle control) | 0601-55612 | Overhaul factory | 3 month after SB receipt |
| 140-BD | 10.02.86 | Preventing destruction of the relay No.7230 box attachment | 0601-55612 | Overhaul factory | MOH |
| 141-BD | 17.07.84 | Reinforcement of the attachment area of elevator control bracket No. 5130-30 | 0601-55612 | Overhaul factory | MOH |
| 142-BU | 06.07.84 | Hole in the trim tab control linkage No.5410-140SB | 0601-55612 | Aircraft manufacturer | MOH |
| 143-BE | 14.07.84 | Operation manual clarification | All | Information bulletin | |
| 144-BD | 20.03.86 | 1.Replacement of wing attachment fittings for thicker ones 2. Replacement of wing attachment bolts | 0601-2011 0601-2010 | Aircraft manufacturer | MOH |
| 145-BR | 11.12.84 | MOH Manual clarification | All | Information bulletin | |
| 146-BD | 01.11.84 | Installation of the fuel breathing system cover No.6100-94 instead of the constrictor | 0601-44604 | Operation within summer season | |
| 147-BU | 28.03.85 | Installation of the first-aid box | 0601-2007 | Overhaul factory | MOH |
| 148-BD | 23.11.84 | Installation of bonding stripes between engine cowling and fuselage | 0601-34027 | Overhaul factory | MOH |
| 149-BU | 26.03.85 | Replacement of the oil system valve No.6204-05 with the steel valve made from 12H18A10T | 0601-55612 | Overhaul factory | MOH |
| 150-BU | 16.04.85 | Replacement of oil tank with the reinforced oil tank No.6201-100 | 0601-37290 | Aircraft manufacturer | MOH |
| 151-BD | 05.09.85 | Reinforcement and replacement of stops No.5130-50 and No.5130-90 in airplane control system | 0601-55612 | Overhaul Factory and Maintenance Organization | |
| 152-BR | 31.05.85 | Clarification of MOH Manual and parts catalogue | All | Information bulletin | |
| 153-BD | 06.02.86 | Replacement of control column attachment bolts with bolts No.3027-6-18, Control column replacement | 0601-55612 | Aircraft manufacturer | MOH |
| 154-BD | 20.02.85 | Installation of the eyebolt No.5410-1410SB in trim tab control system | 0601-55612 | Overhaul factory | MOH |
| 155-BU | 18.04.85 | Installation of spring cylinder on RH landing gear | 34019-34139 | Aircraft manufacturer | MOH |
| 157-BD | 10.04.86 | Replacement of brackets 0161-20, 0161-30 with reinforced ones | 0601-55612 | Both Aircraft Manufacturer and Overhaul Factory | MOH |
| 158-BD | 16.08.85 | Fuel system, modification of drain system | 0601-55612 | Aircraft manufacturer | 16.11.85 |
| 159-BE | 29.05.85 | Manuals clarification (nuts tightening with preselect torque) | 0601-55612 | Aircraft manufacturer | 29.08.86 |
| 160-BE | 18.12.84 | Manuals clarification (increasing time between MOHs) | All | Information bulletin | |
| 161-BD | 29.10.86 | Reinforcement of ribs nose parts attachment to the wing center section front spar | 0601-0730 | Overhaul factory | MOH |
| 162-BD | 16.05.85 | Replacement of the clamp No.6801-110V-7 with the clamp No. 6801-310 | 0601-0730 | Overhaul factory, Operator | On SB receipt |
| 163-BD | 16.05.85 | Replacement of gills bolts No.6303- 171 with higher strength bolts | 0601-55612 | Overhaul factory | MOH |
| 164-BD | 16.08.85 | Replacement of the engine cowling lock case No.6902-81 | 0601-55612 | Overhaul factory, Operator | If cracks found |

| | | | | | |
|--------|----------|---|------------|--|--|
| 165-BD | 14.02.86 | Replacement of throttle handle for the reinforced throttle handle No.7003-20 | 0601-55612 | Aircraft manufacturer | MOH |
| 166-BD | 13.12.86 | Replacement of the R-2 governor pawl No.6500-203 with the improved pawl No.6500-211 | 0601-0730 | Aircraft manufacturer | MOH |
| 167-BD | 13.02.86 | Replacement of carburetor scoop hinge | 0601-55612 | Aircraft manufacturer | MOH |
| 168-BD | 09.06.86 | Replacement of the bracket 6500-10 with the improved bracket 6500-230 | 0601-0730 | Overhaul factory | MOH |
| 169-BD | 02.07.85 | Replacement of the center support bolt No.3000-11 with the bolt 3000-13 | 0601-55612 | Aircraft manufacturer | MOH |
| 170-BD | 16.05.86 | Preventing brake control cable ruptures | 0601-0730 | Overhaul factory | MOH |
| 171-BD | 03.03.86 | Installation of bushings under the PU- 7 valve control screw | 0601-0730 | Maintenance organization | 03.09.86 |
| 172-BU | 29.01.86 | Installation of bushings under shut-off valve handle attachment screw | 0601-55612 | Overhaul factory | MOH |
| 173-BD | 15.01.86 | Replacement of the attachment bracket No.0200-30 on the rear stabilizer attachment point | 0601-55612 | Aircraft manufacturer | MOH |
| 175-BD | 08.04.86 | Installation of the edge former around the oil cooler cut-out | 0601-55612 | Overhaul Factory or Maintenance Organization if cracks found | MOH or during operation, if cracks found |
| 176-BD | 11.05.86 | Air heater modification | 0601-55612 | Overhaul factory | MOH |
| 177-BD | 24.03.87 | Installation of light- and sound- warning system for landing gear retracted position | All | Overhaul factory | MOH |
| 178-BD | 11.12.85 | Changing of the US-450 air speed indicator installation | 0601-55612 | Overhaul factory | 31.12.1986 |
| 179-BD | 14.07.86 | Cockpit doors modification | 0601-55612 | Overhaul factory | MOH |
| 180-BD | 15.05.86 | Reinforcement of bulkhead No.0, No.8 and profile 0100-20 | 0601-55612 | Overhaul factory | MOH |
| 181-BD | 30.10.86 | Replacement of rudder flange and bearing in the lower rudder hinge | 0601-55612 | Overhaul factory | MOH |
| 182-BD | 25.06.86 | Installation of reinforcement plates on the canopy post No.0160-40 | 0601-55612 | Overhaul factory | MOH |
| 183-BD | 27.08.86 | Replacement of aileron attachment bolts No.2000-19 with No.2000-19A | 0601-55612 | Overhaul factory | MOH |
| 185-BD | 15.05.86 | Manuals clarification (regarding air heater) | All | Information bulletin | |
| 186-BD | 25.06.86 | Reinforcement of attachment of ribs tail parts to the wing rear spar | 0601-55612 | Overhaul factory | MOH |
| 187-BE | 24.03.87 | Manuals clarification (regarding bulletin No.177-BD) | All | Information bulletin | |
| 188-BR | 15.06.87 | Clarification of MOH Manual and parts catalogue (regarding bulletin No.177-BD) | All | Information bulletin | |
| 189-BR | 30.10.86 | Clarification of MOH Manual | All | Information bulletin | |
| 190-BD | 29.10.86 | Replacement of the battery access door diaphragm with the reinforced diaphragm No.1020-180-31 | 0601-55612 | Overhaul factory | MOH |
| 191-BD | 29.10.86 | Replacement of the diaphragm which connects tail parts of ribs within the wing center section | 0601-55612 | Overhaul factory | MOH |
| 192-BD | 29.10.86 | Replacement of flaps in the PO-250 access door hinge | 0601-55612 | Overhaul factory | MOH |
| 193-BD | 29.10.86 | Replacement of shapes in the PO- 250 compartment with reinforced shapes | 0601-55612 | Aircraft manufacturer | MOH |

| | | | | | |
|--------|----------|--|--|--|--------------------------|
| 194-BD | 29.10.86 | Replacement of the wing center section step band No.1020-80-90 with new one | 0601-55612 | Overhaul Factory | During operation |
| 195-BD | 08.07.87 | Replacement of teflon washers under the wing fairing attachment bolts | 0601-55612 | Overhaul Factory or Maintenance Organization | MOH or during operation |
| 196-BD | 26.08.86 | Replacement of loose rivets attaching lower skin to the wing center section | 0601-55612 | Overhaul factory | MOH |
| 197-BD | 27.08.86 | Elimination of cracks on the oil cooler inlet. Arc welding | 0601-55612 | Overhaul factory | MOH |
| 198-BE | 08.05.87 | Clarification of weight and balance data | 0601-55612 | Information bulletin | |
| 200-BD | 11.03.87 | Fin skin reinforcement and repair | 0601-55612 | Overhaul Factory | MOH |
| 201-BD | 13.04.87 | Replacement of canopy bracket No. 0161-10 with the reinforced one | 0601-55612 | Overhaul factory | MOH |
| 202-BU | 05.01.87 | Replacement of balls in landing gear jacks | 0601-0730 | Overhaul factory | MOH |
| 203-BD | 13.04.87 | Addendum to the bulletin No.157-BD (regarding canopy brackets replacement) | 0601-2009, 0110-55612 | Information bulletin | |
| 204-BD | 08.05.87 | Installation of the cover No.9960-120 for the DS-1 sender protection | 0601-47817 | Aircraft manufacturer | During operation |
| 205-BE | 08.05.87 | Clarification of the bulletin No.173-BD (bracket replacement after 2000 flight hours) | 0601-55612 | | After 2000 flight hours |
| 206-BR | 10.11.87 | Clarification of MOH Manual and parts catalogue | All | Information bulletin | |
| 207-BD | 01.09.87 | Replacement of control column locking bolts and their wire locking | 0601-55612 | Overhaul Factory | MOH |
| 208-BD | 02.09.87 | Replacement of shapes attaching ribs to the front wing spar | All | Overhaul Factory | MOH |
| 209-BD | 04.04.88 | Modification of fuel breathing system | 0601-55612 | | |
| 211-BD | 04.04.88 | Manuals clarification (regarding bulletin No.209-BD) | 0601-55612 | Information bulletin | |
| 212-BR | 04.04.88 | MOH Manual clarification (regarding bulletin No.209-BD) | All | Information bulletin | |
| 215-BD | 19.02.88 | Replacement of the MU-615 sender attachment (SARPP-12K system) | 0601-55612 | Overhaul Factory | MOH |
| 222-BD | 16.01.89 | Enclosure of part 1 of SB 028-DK to S/N 0115-2220255612 | 0115-55612 | Aircraft manufacturer | During operation |
| 251-BE | 05.02.99 | Clarification of SB 205-BE | 0601-55612 0131 and up | Operator, Overhaul factory | 1 month after SB receipt |
| 252-BE | 05.02.99 | Clarification of SB 173-BE | 0601-55612 0131 and up | Operator, Overhaul factory | 1 month after SB receipt |
| 253-BE | 05.02.99 | Control system, Replacement of control column attachment bolts, Clarification of SB 153-BE | 0601-55612 0131-1534 | Operator, Overhaul factory | 1 month after SB receipt |
| 254-BD | 13.02.07 | Installation of ELT ARM-406AC1 | 0601-0730, 0131-2035, Excl. 0233, 0234,0334, 0431, 0434, 0534, 0634, 0932, 1134, 1433,1633 | | |
| 255-BD | 14.05.08 | Modernization of Yak-18T | | Information bulletin | |

| | | | | | |
|----------|----------|---|---|-----------------------|-------------|
| 256-BU | 07.04.09 | Use of propeller AV-803-1-K- C/CL250-412 or B530TA-D35 on aircraft 36 th series and a/c modified iaw. SB 255-BD | A/C of 36 th series and a/c modified iaw. SB 255-BD | Information bulletin | |
| 257-BE | 07.04.09 | Powerplant, Amended AMM and AFM | If SB 256-BU installed | | |
| 258-BD | 09.06.09 | Instrument panel, Horizon 4300-311 | 0136-4936, and S/N modified iaw. SB 255-BD: 0334, 0534, 1134, 0431, 1433, 0636, 1633, 0932, 0434. | Aircraft manufacturer | 01.09.2009 |
| 259-BD | 09.06.09 | Wing, additional rivets on wing spar | 0136-2336, 2636-4336 | Aircraft supplier | 15.07.2009 |
| 260-BD | 09.09.09 | Fuel system, Replacement of parts in drain system and fuel sensor 395-5S- 1B | 0136-4336 | Aircraft supplier | 20.10.2009 |
| 261-BE-G | 06.05.11 | Conditions and order of establishment of resources and service life of airplanes Yak-18T brought in the State Register of Civil Aircrafts of the Russian Federation (MS-1000 & MS-2000) | All | Aircraft manufacturer | Permanently |

Notes

SB marked in Green are Mandatory.

No Mandatory Service Bulletins (Airworthiness Directives) have been issued subsequent to 1998.

MOH = Major Overhaul at a Yakovlev certified facility

Source: Yakovlev Design Bureau, EASA 2013